

**MARYLAND HISTORICAL TRUST  
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes ☐  
no ☐

Property Name: Gwynnbrook Farm House Inventory Number: BA-1746  
Address: 11767 Owings Mills Boulevard Historic district: ☐ yes ☒ no  
City: Owings Mills Zip Code: 21117-2810 County: Baltimore County  
USGS Quadrangle(s): Reisterstown  
Property Owner: State of Maryland Department of Game and Inland Fish Tax Account ID Number: 0419072275  
Tax Map Parcel Number(s): 164 Tax Map Number: 58  
Project: Gwynnbrook Avenue Bridge Replacement Agency: Baltimore County Dept of Public Works  
Agency Prepared By: Whitman, Requardt and Associates, LLP  
Preparer's Name: Sheryl Bernardo Date Prepared: 4/5/2004  
Documentation is presented in: Maryland Historical Trust Inventory Form For State Historic Sites Survey  
Preparer's Eligibility Recommendation: ☒ Eligibility recommended ☐ Eligibility not recommended  
Criteria: ☐ A ☐ B ☒ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G  
*Complete if the property is a contributing or non-contributing resource to a NR district/property:*  
Name of the District/Property: \_\_\_\_\_  
Inventory Number: \_\_\_\_\_ Eligible: ☐ yes Listed: ☐ yes  
Site visit by MHT Staff ☐ yes ☒ no Name: \_\_\_\_\_ Date: \_\_\_\_\_

**Description of Property and Justification:** *(Please attach map and photo)*

The following information has been reported in the Maryland Historical Trust Inventory Form for State Historic Sites Survey for BA 1746 (updated site inventory on 04-05-04).

Gwynnbrook House located on the north side of Gwynnbrook Avenue and east of Bonita Avenue and the Western Maryland Railroad, is a curious two storey, three bay wide, one bay deep structure constructed of brick which is layed out in a Flemish bond

**MARYLAND HISTORICAL TRUST REVIEW**

Eligibility recommended ☒ Eligibility not recommended ☐  
Criteria: ☐ A ☐ B ☒ C ☐ D Considerations: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G  
MHT Comments:

Tom Tinkum  
Reviewer, Office of Preservation Services

5/18/04  
Date

Blum  
Reviewer, National Register Program

5/18/04  
Date

200401192

NR-ELIGIBILITY REVIEW FORM

BA 1746

Gwynnbrook Farm House

Page 2

style. A slightly lower two-storey two bay wide, one bay deep wing also of brick laid in Flemish bond extends from the west gable façade. A two-storey German-sided (frame) addition of equal height to the main block project from the central bay of the rear north façade of this section. The frame section has a one storey lean-to addition along its two bay east façade. On the second storey in the southern bay of this section a flat roofed one bay addition has been constructed. Both these sections are also sheathed with German siding. A screened porch projects from the rear (north) façade of the lower brick addition. The over-all configuration of this dwelling yields and "L" shaped plan. (The brickwork has been painted white.)

The principal (south) façade of the main block is defined by a central doorway flanked by 12/2 sashed windows of the first storey. On the second storey from east to west the three corresponding openings yield 6/6, 6/6, and 9/6 sashed windows respectively. All but the second storey 9/6 sash are replacement shashes in one form or another. Windows on both levels are framed by architrave surrounds with projected wooden sills. Pegging is still evident on most of the window frames. A three-course brick belt course projects between the first and second storeys. A one-storey, one-bay screened portico shelters the main entrance. Tuscan columns serve as supports. The door, framed by a molded surround and single light transom, is six paneled.

The main block rests on a low brick foundation defined by a molded brick water table. Due to the westward slope of the land the water table is higher towards the western bays. (The lower two storey bay rests on an exposed stone foundation that has been painted white to match the white brickwork.)

(The roof is shingled in cedar shake that includes the main house and the addition.)

Corbel-capped interior brick chimneys are found at both gabled ends.

On the rear (north) façade, because of the network of frames additions, only the first and second storey windows of the western bay are visible to exterior. The first storey window is 9/6 sash; the second storey window is 6/6. Both are framed by an architraved surround with projecting wood sill.

The east gable end, laid in common bond brick is distinguished by two, four-light, five-sashed windows at attic level and boxed cornice returns.

The west gable façade yields only the boxed cornice returns.

Architecturally, the house dates from possible as early as eighteenth century with later additions and alterations. A surprising amount of original interior trim remains intact.

The Gwynnbrook Farmhouse (BA-1746) has been documented in the Maryland Historical Trust Inventory Form for State Historic

**MARYLAND HISTORICAL TRUST REVIEW**

Eligibility recommended \_\_\_\_\_

Eligibility not recommended \_\_\_\_\_

Criteria: \_\_\_\_ A \_\_\_\_ B \_\_\_\_ C \_\_\_\_ D Considerations: \_\_\_\_ A \_\_\_\_ B \_\_\_\_ C \_\_\_\_ D \_\_\_\_ E \_\_\_\_ F \_\_\_\_ G

MHT Comments:

\_\_\_\_\_  
Reviewer, Office of Preservation Services

\_\_\_\_\_  
Date

\_\_\_\_\_  
Reviewer, National Register Program

\_\_\_\_\_  
Date

NR-ELIGIBILITY REVIEW FORM

BA 1746

Gwynnbrook Farm House

Page 3

Sites Survey indicating that the site has historical significance. It is our determination that this property should be regarded as significant and should be eligible for inclusion in either the Maryland Register of Historic Properties or the National Register of Historic Places. Eligibility should be based on Criteria C: Architecture as described as "embodiment of distinctive characteristics of a type, period, method of construction or the work of a master, or that possess high artistic values or that represent a significant and distinguishable entity whose components may lack individual distinction." The Gwynnbrook Farm House is not part of a National Register Historic District. Architecturally, the property dates from as early as the 18th Century with later additions and alterations. The significant qualities that make this property important is that the main house is a typical Federal Style Characteristic from central Maryland farmhouses.

The historic resource boundary for the Gwynnbrook Farmhouse has been delineated on an attached aerial photograph. Natural landscape features surrounding the property were used in determining the resource boundary. Beginning on the western edge of the property, the boundary is defined by an evergreen landscape buffer, to the north it is defined by specimen trees, to the east it is defined by an access driveway, and to the south by an end of the circle driveway in front of the property. This setting provides a natural delineation for this important historic resource.

04 05 04

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended \_\_\_\_\_

Eligibility not recommended \_\_\_\_\_

Criteria: \_\_\_ A \_\_\_ B \_\_\_ C \_\_\_ D Considerations: \_\_\_ A \_\_\_ B \_\_\_ C \_\_\_ D \_\_\_ E \_\_\_ F \_\_\_ G

MHT Comments:


\_\_\_\_\_  
Reviewer, Office of Preservation Services

\_\_\_\_\_  
Date


\_\_\_\_\_  
Reviewer, National Register Program

\_\_\_\_\_  
Date

# BA - 1746 Gwynnbrook Farm House Historic Resource Boundary Map



# Gwynnbrook Farm House



BALTIMORE COUNTY





BA 1746

Gwynnbrook Farmhouse

Baltimore County, MD

photographer: Sheryl Bernardo

Date of Photo: 3-30-04

009 # 3 1JUN04 CUS ONE HOUR PHOTO

Location of Negative: MD SHPO

South Facing Front Elevation

photo 1 of 7





BA 1746

Gwynnbrook Farm house

Baltimore County, MD

photographer: Sheryl Bernardo

Date of photo: 3-28-04

009 11 9 13JUN04 CUS ONE HOUR PHOTO

Location of Negative: MD SHPO

East Facing Side Elevation

photo 2 of 7



BA1740

Gwynnbrook farmhouse

Baltimore County, MD

photographer: Sheryl Bernard

009 #16 1JUN04 CVS ONE HOUR PHOTO

Date of photo: 3-30-04

Location of Negative: MO SHPO

North Facing Rear Elevation

Photo - 3 of 7



BA 1746

Gwynnbrook Farm house

Baltimore County, MD

Photographer: Sheryl Bernardo

Date of Photo: 3-30-04

009 #18 1JUN04 CUS ONE HOUR PHOTO

Location of Negative: MD SHPO

West Facing Side Elevation

photo 4 of 7





BA 1746

Gwynnbrook Farm house

Baltimore County, MD

photographer: Sheryl Bernardo

Date of photo: 3-30-04

009 #11 1JUN04 CUS ONE HOUR PHOTO

Location of Negative: MD SHPO

View north of shed behind farm house

Photo 5 of 7



BA 1746

Gwynnbrook Farmhouse

Baltimore County, MD

Photographer: Sheryl Bernardo

Date of Photo: 3-30-44

009 # 4 131104 CUS ONE HOUR PHOTO

Location of Negative: MD SHPO

View Southeast toward  
Gwynnbrook Avenue Bridge

photo 6 of 7



BA 1746

Gwynnbrook Farm house

Baltimore County, MD

photographer: Sheryl Bernardo

009 # 5 13JUN04 CUS ONE HOUR PHOTO

Date of Photo: 3-30-04

Location of Negative: MDSHPO

View South Toward Entrance Drive

Photo 7 of 7

ADDENDA

In 1984 the Department of Natural Resources contracted with Joe Getty to conduct a follow-up survey of selected historic properties on DNR lands. DNR funded the field survey and photography but did not prepare finished copy. The attached photocopy pages were forwarded to the Maryland Historical Trust to supplement existing files. All original material and photographs remain in the possession of the Department of Natural Resources under the supervision of Ross Kimmel (x3771).



DRAFT

BA-1746

MEMO

TO: Ross Kimmel, State Historian

From: Joe Getty, Architectural Surveyor

Date: March 23, 1984

Subject: Gwynnbrook House, Gwynnbrook National Resources Management  
Area

At your request, I visited this property and reviewed the documentation in the 1979 inventory form on the house. I was unable to view the interior of the house because no one could find keys that would gain access to the interior.

The original inventory form is accurate except for one area.

The structure consists of a three-bay main block and a two-bay wing constructed along a sloping site. The inventory form refers to the wing as an addition, but it is actually an original part of the house. There is no seam in the brickwork between the two sections. This main block and wing on a sloping site arrangement is a typical Federal-style characteristic for central Maryland farmhouses.

## INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC

AND/OR COMMON

Gwynnbrook House

**2 LOCATION**

STREET &amp; NUMBER

north side of Gwynnbrook Avenue east of Bonita Avenue

CITY, TOWN

CONGRESSIONAL DISTRICT

Reisterstown

VICINITY OF

STATE

Maryland

COUNTY

**3 CLASSIFICATION**

## CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

## OWNERSHIP

☒ PUBLIC☐ PRIVATE☐ BOTH

## PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

## STATUS

☐ OCCUPIED☒ UNOCCUPIED☐ WORK IN PROGRESS

## ACCESSIBLE

☒ YES: RESTRICTED☐ YES: UNRESTRICTED☐ NO

## PRESENT USE

☐ AGRICULTURE☐ MUSEUM☐ COMMERCIAL☒ PARK☐ EDUCATIONAL☐ PRIVATE RESIDENCE☐ ENTERTAINMENT☐ RELIGIOUS☐ GOVERNMENT☐ SCIENTIFIC☐ INDUSTRIAL☐ TRANSPORTATION☐ MILITARY☐ OTHER:**4 OWNER OF PROPERTY**

NAME

Maryland Department of Natural Resources

Telephone #:

STREET &amp; NUMBER

Tawes State Office Building

CITY, TOWN

Annapolis

VICINITY OF

STATE, zip code  
Maryland 21401**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Baltimore County Courthouse

Liber #: 2146

Folio #: 167

STREET &amp; NUMBER

CITY, TOWN

Towson, Maryland

STATE

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR  
SURVEY RECORDS

CITY, TOWN

STATE

**7 DESCRIPTION**

BA-1746

**CONDITION**

☐ EXCELLENT      ☐ DETERIORATED  
☐ GOOD            ☐ RUINS  
☒ FAIR             ☐ UNEXPOSED

**CHECK ONE**

☒ UNALTERED  
☐ ALTERED

**CHECK ONE**

☒ ORIGINAL SITE  
☐ MOVED      DATE \_\_\_\_\_

**DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE**

Gwynnbrook house located on the north side of Gwynnbrook Avenue east of Bonita Avenue and the Western Maryland Railroad is a curious two-storey, three bay wide, one bay deep structure constructed of brick which is laid in flemish bond. A slightly lower two-storey two bay wide, one bay deep wing also of brick laid in flemish bond extends from the west gable facade. A two-storey, german-sided addition of equal height to the main block projects from the central bay of the rear (north) facade of this section. The frame section has a one storey lean-to addition along its two-bay east facade. On the second storey in the southern bay of this section a flat-roofed one bay addition has been constructed. Both these sections are also sheathed with german-siding. A screened porch projects from the rear (north) facade of the lower brick addition. The over-all configuration of this dwelling yields an "L" shaped plan.

The principle (south) facade of the main block is defined by a central doorway flanked by 12/2 sashed windows of the first storey. On the second storey from east to west the three corresponding openings yield 6/6, 6/6 and 9/6 sashed windows respectively. All but the second storey 9/6 sashed window are replacement sash in one form or another. Windows on both levels are framed by architraved surrounds with projected wooden sills. Pegging is still evident on most of the window frames. A three-course brick belt course projects between the first and second storeys. A one-storey, one-bay screened portico shelters the main entrance. Tucson columns serve as supports. The door, framed by a molded surround and single light transom, is six-paneled.

The main block rests on a low brick foundation defined by a molded brick water table. Due to the westward slope of the land the water-table is higher towards the western bays.

An asphalt-shingled-over-wood-shingled gable roof ends in a box cornice with a molded fascia beneath. This band stops approximately eight inches short of both ends of the main facade.

Corbel-capped interior brick chimneys are found at both gable ends.

On the rear (north) facade, because of the network of frame additions, only the first and second storey windows of the western bay are visible to exterior view. The first storey window is 9/6 sash; the second storey window is 6/6. Both are framed by an architraved surround with projecting wood sill.

The east gable end, laid in common bond brick is distinguished by two, four-light, five-sashed windows at attic level and boxed cornice returns.

The west gable facade yields only the boxed cornice returns.  
CONTINUE ON SEPARATE SHEET IF NECESSARY

**8 SIGNIFICANCE**

BA-1746

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

## STATEMENT OF SIGNIFICANCE

A chain of title search yields little conclusive information with regard to the history of this structure.

The tract of land on which this dwelling sits is known as "Thomas Advancement" was surveyed by Thomas Wells September 15, 1732.<sup>1</sup> In 1734 he received a patent for his fifty-acre parcel.<sup>2</sup>

Shortly thereafter Wells married Elizabeth Howard at Saint Paul's Episcopal Church in Baltimore County on September 16, 1736. (Elizabeth Howard was a daughter of Joshua and Joanna Howard a prominent early eighteenth century family of Green Springs Valley. Their house Grey Rock is located along Reisterstown Road near Pikesville.) Their children were Francis who married Ann Tevis, Joseph who married Susanna Tevis then Betsy Owings, John who married Dinah Cromwell, James, Thomas, Jr. who married Mary Major, Richard who died young and Ann, their only daughter who married Robert Crawford.<sup>3</sup>

Wells appears to have been very active in the Episcopal Church. In May of 1741 Reverend Benedict Bourdillon proposed to the vestry of Saint Paul to build "by free subscription a chapel of ease...", Thomas Wells was listed as a private and voluntary subscriber for the building of the new parish, St. Thomas.<sup>4</sup>

The 1850 J. C. Sidney Map of the City and County of Baltimore, Maryland from Original Surveys shows the dwelling owned by a Cardiff Tagart. Land records confirm the ownership. He acquired the property 297 1/4 acres in 1834 from the estate of John Tagart. Cardiff Tagart also owned a sizeable nearby parcel of land included in the tract known as "Risteau's Garrison."<sup>6</sup> It was on this piece of property where he resided, for at his death in 1881 his estate appraised the 225-acre tract called "Garrison" which included a two-storey stone and frame house. This house refers to his the one located on his Fort Garrison Farm Property.<sup>8</sup> Tagart was also involved in the activities of Saint Thomas Church. He was a vestryman in 1841, 1843, 1844 and 1852 and a church warden in 1846. Upon his death he gave a generous sum of money to the church.<sup>5</sup>

CONTINUE ON SEPARATE SHEET IF NECESSARY

BA-1746

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

See footnotes

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE \_\_\_\_\_ COUNTY \_\_\_\_\_

STATE \_\_\_\_\_ COUNTY \_\_\_\_\_

**11 FORM PREPARED BY**

NAME / TITLE

Bridget M. Deale, Historic Sites Surveyor

ORGANIZATION

Maryland Historical Trust

STREET & NUMBER

21 State Circle

CITY OR TOWN

Annapolis,

DATE

TELEPHONE

269-2438

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438



The lower two-storey brick wing also laid in flemish bond is defined by a doorway in the eastern bay and a window in the western bay of the first storey. Two windows occupy the corresponding openings of the second storey. The windows are universally 2/2 sashed with plain wooden surrounds and projecting timber sills. The slightly recessed, six-paneled door is framed by a plain wooden surround. Jamb and head areas are blanks.

The asphalt-shingled-over wood-shingled roof ends in a boxed cornice with a molded fascia beneath which, like that of the main block, stops approximated eight inches short of the end.

A corbel-capped interior brick chimney is located in the west gable facade.

The west gable facade is without fenestration except for two, four light, fixed sashed windows at attic level. This area is further defined by boxed cornice returns.

The interior has suffered little alteration. The main entrance leads into the hall and secondary parlor. To the east of this room is the primary parlor. The hall/parlor yields a molded chair rail and baseboards as well as architraved window and door surrounds. Windows are also framed by eight-inch reveals. An elaborate multi-molded mantel is located on the west wall.

The main parlor also yeilds molded chairrail and baseboards. Windows are framed by architraved surround. The south window is recessed in an eight inch reveal while the north window is blocked up. An elaborate multi-molded mantel is located on the east wall. It is flanked by built-in cupboards possessing four open shelves above paneled cabinets.

Access to the brick addition is found in the southern end of the west wall of the main block. A six-paneled door was cut to fit the newer expanded entry. (Quite possibly this was originally an exterior door.) Three steps lead down to the one room brick addition.) This room yields planer window and door surrounds. The door on the south wall is six-paneled. Windows are recessed in shallower reveals. A less elaborate mantel is found on the west wall. Enclosed stairs are located in the northeast corner.




The G. M. Hopkins 1877 Atlas of Baltimore County indicates that the Gwynnbrook dwelling was occupied by Charles A. Reese. He is listed as a farmer from Baltimore County. Land Records information however shows that the property is owned by John Gingrich of Daufsin County Pennsylvania.<sup>9</sup> Charles A. Reese is also cited on George W. and Walter S. Bromley's 1898 Atlas of Baltimore County, Maryland, from Actual Surveys & Official Plans.

[probably incorrect; checked 1877 atlas  
"Mrs." - Ed Nelson instead 6-11-96]

Throughout the 20th century, until the State of Maryland purchased the property in 1952 the property remained in the Dolfield family.<sup>10</sup>

Architecturally, the house dates from possibly as early as eighteenth century with later additions and alterations. A surprising amount of original interior trim remains intact despite the building's current unoccupied status. The building however is in need of immediate attention. The west gable end is severely bowed. The east gable end at ground level is threatened by the continual erosion of the surrounding hilly terrain.

- 1) E. 1 #2/93 Hall of Records Annapolis, Maryland.
- 2) IBID.
- 3) Maryland Historical Magazine XL 1945, Baltimore, Maryland, p. 322.
- 4) Scharf, J. Thomas, History of Baltimore City and County, Baltimore, Maryland, p. 857.
- 5) Land Records of Baltimore County, J. K. 239/181
- 6) Thomas, Dawn; The Green Spring Valley: Its History and Heritage, Volume One. Baltimore, Maryland, p.269.
- 7) IBID.
- 8) IBID, p.270.
- 9) Land Records of Baltimore County HMF 4/506.
- 10) Land Records of Baltimore County 518/44.



BA-1746

U.S.G.S. MAP

REISTERSTOWN, MD.



GWYNNBROOK HOUSE

BA 1746

NORTH SIDE OF GWYNNBROOK AVE.

DNR 1

REISTERSTOWN, MARYLAND

GWYNNBROOK WMA

SOUTH ELEVATION

5/79 BMD



BA 1746  
PNR 1

GWYNNBROOK HOUSE  
NORTH SIDE OF GWYNNBROOK AVENUE  
REISTERSTOWN, MARYLAND

GWYNNBROOK WHA

EAST ELEVATION

5/79 BMD






BA-1746

DNR-1

GWYNNBROOK HOUSE  
NORTH SIDE OF GWYNNBROOK AVENUE  
REISTERSTOWN, MARYLAND

WINDOW DETAIL

BMD; 5/79




BA-1746

DNR-1

GWYNNBROOK HOUSE  
NORTH SIDE OF GWYNNBROOK AVENUE  
REISTERSTOWN, MARYLAND

EXTERIOR DOOR(MAIN WING)

BMD;5/79



BA-1746

DNR-1

Gwynnbrook House  
North side of Gwynnbrook Avenue  
Reisterstown, Maryland

Molding Detail

BMD;5/79

MANUFACTURED  
BY KODAK






BA-1746

DNR-1

GWYNNBROOK HOUSE  
NORTH SIDE OF GWYNNBROOK AVENUE  
REISTERSTOWN, MARYLAND

PARLOR MANTEL, CUPBOARD

BMD 5/79



BA-1746

DNR-1

GWYNNBROOK HOUSE  
NORTH SIDE OF GWYNNBROOK AVENUE  
REISTERSTOWN, MARYLAND

EXTERIOR DOOR(ADDITION)

BMD 5/79